

NOTICE INSTALLER

After removing the Cutter/Mixer from skid, install the following parts enclosed: The feet must be installed to prevent the Cutter/Mixer from moving during operation.

Part No.	Part Name	Amt.
C-122164	#1 Foot	2
C-122165	#2 Foot	2
SC-117-97	Fin. Bolt - ½" - 13 x 1"	4
WS-21-9	Washer	4

Apply a bead of silastic sealer around the edge of each leg. Next, insert the feet in their proper location. Install the finished bolts and washers and tighten the bolts to hold the feet in place.



Form 12864 Rev. A

TROY, OHIO 45374

Printed in U.S.A.

NOTICE INSTALLER

After removing the Cutter/Mixer from skid, install the following parts enclosed: The feet must be installed to prevent the Cutter/Mixer from moving during operation.

Part No.	Part Name	Amt.
C-122164	#1 Foot	2
C-122165	#2 Foot	2
SC-117-97	Fin. Bolt - ½" - 13 x 1"	4
WS-21-9	Washer	4

Apply a bead of silastic sealer around the edge of each leg. Next, insert the feet in their proper location. Install the finished bolts and washers and tighten the bolts to hold the feet in place.



Form 12864 Rev. A

TROY, OHIO 45374

Printed in U.S.A.

NOTICE INSTALLER

After removing the Cutter/Mixer from skid, install the following parts enclosed: The feet must be installed to prevent the Cutter/Mixer from moving during operation.

Part No.	Part Name	Amt.
C-122164	#1 Foot	2
C-122165	#2 Foot	2
SC-117-97	Fin. Bolt - ½" - 13 x 1"	4
WS-21-9	Washer	4

Apply a bead of silastic sealer around the edge of each leg. Next, insert the feet in their proper location. Install the finished bolts and washers and tighten the bolts to hold the feet in place.



Form 12864 Rev. A

TROY, OHIO 45374

Printed in U.S.A.